

OPTISABER®

A DOMAILLE SOLUTION

PRODUCT LIST



OS7100



OS7000M



OS7000S








OS7500P

CONTENTS

Laser Cleavers.....	pages 3-4
OS7000S Adapters.....	pages 5-7
OS7100 Adapters.....	pages 8-10
Monitors.....	pages 11-12
Cables & Power Supplies.....	pages 13-14
Accessories/Replacement Parts.....	pages 15-18

Laser Cleavers

Image	Part Number Description
	OS7100 Universal Laser Cleaver
	OS7000M Multifiber Laser Cleaver
	OS7000M-TMT TMT Multifiber Laser Cleaver
	OS7000S Single Fiber Laser Cleaver












OS7500P


Prizm, MXC Laser Cleaver

Adapters sold separately

OS7000S Adapters

Image	Part Number Description
	ON15112 Adapter, LC
	ON15113 Adapter, SC
	ON15114 Adapter, SMA
	ON15115 Adapter, FC

	ON15116 Adapter Insert, ST, E2000
	ON15117 Adapter Insert, M29504/4
	ON15118 Adapter Insert, M29504/5
	ON15119 Adapter Insert, M29504/14/15
	ON15120 Adapter Insert, Ø1.25 Ferrule



ON15123

Adapter Insert, Ballistix/SC W/O
Housing

OS7100 Adapters





Image	Part Number Description
 OS71-SC-A SC Connector DOMAILLE ENGINEERING	OS71-SC Adapter, SC
 OS71-LC LC Connector DOMAILLE ENGINEERING	OS71-LC Adapter, LC
 OS71-MT MT FERRULE DOMAILLE ENGINEERING PATENT PENDING	OS71-MT Adapter, MT
 OS71-TMT TMT FERRULE DOMAILLE ENGINEERING PATENT PENDING	OS71-TMT Adapter, TMT

Image Currently Unavailable	OS71-FC Adapter, FC
Image Currently Unavailable	OS71-SMA Adapter, SMA
Image Currently Unavailable	OS71-M29504-4-5 Adapter, M29504/4 & /5
Image Currently Unavailable	OS71-200X40 Adapter, Ø2.0mm X 4mm Ferrule, M29504/14 & /15
Image Currently Unavailable	OS71-125X49 Adapter, Ø1.25mm X 4.9mm ferrule only, ARINC 801 & LC Ferrule Only


**Image Currently
Unavailable**

OS71-250X79

Adapter, Ø2.5mm X 7.9mm ferrule
only, ST, SC ferrule only, E2000
ferrule only (8.3mm long)

Monitors

Image	Part Number Description
	DE19408 12.1" LCD Monitor, Metal Frame
	DE19408-ST Stand, 12.1" Metal Monitor
	ON12182 13.3", Industrial HDMI Touch Monitor for OS7100
	ON12183 Monitor Mount for ON12182



ON12184

Arm w/Elbow for ON12182





ON12185

AMPS Mount for ON12182

Cables & Power Supplies

Image	Part Number Description
	ME-12011 BNC/BNC Cable 6ft (305mm)
	ME-12016 Power Cord, US
	CO12018 Power Cord, US OS7100
	PM32086 Power Cord, CHINA
	PM22130 Power Cord, EURO
	PM22129 Power Cord, UK

	ME-12422 Power Supply w/4 Adapters OS7100
	ON12208 HDMI Cable for Monitor (ON12182) OS7100
	ON12115 Ethernet Cable
	ON12214 USB Cable OS7100
	ON15003 Power Supply Assembly OS7000M, OS7000-TMT, OS7000S, OS7500P
	ON15018 Power Supply Assembly OS7100

Accessories/Replacement Parts

Image	Part Number Description
	ON15000 Laser Control Box
	ON15011 Footswitch w/Cord
	ON15012 Hand Switch w/Cord
	ON15014 Cyclone Separator
	ON15015 Extract Replacement Hose & Cuffs
	ON12001 Extract Unit, 120V *Includes Extract Cube (Single Port), Main Filter, Connection Kit, 120V Plug Lead*

	ON12002 Extract Unit, 220V *Includes Extract Cube (Single Port), Main Filter, Connection Kit, 230V Plug Lead*
	ON12226 Blower Motor Kit
	ON10040 Filter Main Unit
	ON12083 Extract Prefilter
	ON12084 Extract Main Filter
	ON12054 Fan Filter Assembly
	ON10042 Height Adjust Wheel


	ON10043 Height Adjust Rod
	KNOBKNURLM4BLACK Knob
Image Currently Unavailable	ON12005 Shipping Case
	ON12169 Camera Assembly OS7000S, OS7000M, OS7000M-TMT
	ON12114 Camera Lens OS7100
	ON12181 Raspberry Pi Camera OS7100
	ON12224 Knob Control for Extract Unit

Image Currently Unavailable	ON12225 Spindle Potentiometer for Extract Unit
	ON12132 Angled Brush
	PF-2.5 BRUSH Cleaning Brush